

Problems with daily training and usage - /Bug #1329

RNAV RPLL 06 FLS not aligned with PAPI

05/20/2025 02:14 AM - sim tech

Status:	InProgress	Start date:	05/19/2025
Priority:	Medium	% Done:	0%
Assignee:		Spent time:	0.00 hour
Category:			
Target version:			
Reporter:	simtech	FlightPhase:	Landing
Phone:	09063489642	100%Reproducible:	YES
PlannedFixDate:	08/31/2025	ReproductionSteps:	Init Step Issue Expect
SoftVersion:	a320-1.9.15	IssueType:	SoftSystem(FunctionLogic)
Description RNAV RPLL 06 FLS not aligned with PAPI			

History

- #1 - 05/20/2025 03:33 PM - Zhou Yanan
- Status changed from /Remains to /New

- Assignee changed from Zhou Yanan to

- IssueType SoftSystem(FunctionLogic) added

- IssueType deleted (Visual)
- #2 - 05/21/2025 08:41 PM -
- Status changed from /New to /InProgress

- PlannedFixDate changed from 05/31/2025 to 08/31/2025

The improvement of FLS functions and consistent with PAPI lights requires modification and improvement of the current solution, which takes about three months.