

Problems with daily training and usage - /Bug #1342

T/O speed using VOMM/VOHS too low

05/30/2025 04:25 AM - sim tech

|   |             |                           |   |
|---|-------------|---------------------------|---|
| <b>Status:</b>  | /Closed     | <b>Start date:</b>        | 05/29/2025                                  |
| <b>Priority:</b>  | Medium      | <b>% Done:</b>            | 0%  |
| <b>Assignee:</b>  | sim tech    | <b>Spent time:</b>        | 0.00 hour                                   |
| <b>Category:</b>  |             |                           |   |
| <b>Target version:</b>  |             |                           |   |
| <b>Reporter:</b>  | Erika Amio  | <b>FlightPhase:</b>       | Takeoff                                     |
| <b>Phone:</b>   | 09063489642 | <b>100%Reproducible:</b>  | YES   |
| <b>PlannedFixDate:</b>  | 06/04/2025  | <b>ReproductionSteps:</b> | Init<br><br>Step<br><br>Issue<br><br>Expect |
| <b>SoftVersion:</b>   | a320-1.9.15 | <b>IssueType:</b>         | CLS   |
| <b>Description</b>  |             |                           |   |
| Remark on May 23 fly-out  |             |                           |   |
| T/O speed using VOMM/VOHS charts indicates speeds are too low when TO config check is performed |             |                           |   |

History

- #1 - 06/04/2025 03:07 PM - Zhou Yanan
- Status changed from /Remains to /FeedBack

- Assignee changed from Zhou Yanan to sim tech
- The takeoff speed on the IOS platform may differ from the calculated takeoff speed by the FLY SMART software. It is provided for reference only. For an accurate takeoff speed, please refer to FLY SMART.
- #2 - 08/07/2025 10:45 AM - Hugues Lemire
- Tested during last quality flyout last July 15th and the crew deemed the T/O speeds to be normal. Please close this issue at your earliest convinience.
- #3 - 08/07/2025 10:46 AM - Hugues Lemire
- Status changed from /FeedBack to /Closed