

	2025-12				2026-1					2026-2				2026-3				2026-4				2026-5				
	49	50	51	52	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
Problems with daily training and usage																										
The oxygen value of the oxygen cylinder cannot (...)																										
The runways of some general airports are (...)																										
TRAFFIC ON RUNWAY CANNOT BE REMOVED (DESPITE (...)																										
LANDING MEMO NOT DISPLAYED DURING DESCEND (...)																										
NOT ENOUGH YAW MOVEMENT DURING ENGINE FAILURE (...)																										
NO LOCKING MECHANISM FOR THE DOOR OF THE (...)																										
TRAFFIC APPEAR (B747) ON TOP AFTER PUSH BACK. (...)																										
The fault of saving the flight plan with (...)																										
RNAV RPLL 06 FLS not aligned with PAPI																										
Sound not audible																										
Emer Elec config fail																										
No motion cues for Engine compressor stall (...)																										
Aircraft position slew on the IOS is too (...)																										
UPRT and Windshear handling is too easy																										
Emergency service vehicles are not available (...)																										
NW Steering fault should show "CAT III Dual" (...)																										
Ambient Light LEDs that are simulating sunlight (...)																										
Debrief Camera UI is in Chinese only																										
Router UI is in Chinese only																										
No aural EGPWS warning on NEO																										
Abrupt/Shaking movement then motion goes (...)																										