# Problems with daily training and usage - 　　/Bug #1346

## Aircraft position slew on the IOS is too slow

05/30/2025 04:50 AM - sim tech

| | | | |
|---|---|---|---|
| **Status:** | 　　/InProgress | **Start date:** | 05/29/2025 |
| **Priority:** | Medium | **% Done:** | 0% |
| **Assignee:** | Zhou Yanan | **Spent time:** | 0.00 hour |
| **Category:** | | | |
| **Target version:** | | | |
| **Reporter:** | Hugues Lemire | **FlightPhase:** | Taxing |
| **Phone:** | 09063489642 | **100%Reproducible:** | YES |
| **PlannedFixDate:** | 06/04/2025 | **ReproductionSteps:** | Init |
| | | | Step |
| | | | Issue |
| | | | Expect |
| **SoftVersion:** | a320-1.9.15 | **IssueType:** | Others |

**Description**

When holding the aircraft position slew button on the IOS slew page, it take way to long (more than 10sec) before the position moves rapidly. Heading and altitude slew speeds are ok.

## History

**#1 - 06/04/2025 02:05 PM - Zhou Yanan**

*- Status changed from 　　/Remains to 　/New*

*- Assignee changed from Zhou Yanan to 　*

Please provide a method for quick slewing.

**#2 - 06/04/2025 02:17 PM - Zhou Yanan**

Please add a quick SLEW button on the IOS interface. When pressed, it will instantly increase the SLEW speed to five times the current maximum speed. This function should be available in all directions: front, back, left and right.

**#3 - 06/04/2025 03:36 PM - 　**

*- Assignee changed from 　 to 　*

**#4 - 06/06/2025 04:39 PM - 　**

*- Status changed from 　/New to 　　/BeVerified*

*- Assignee changed from 　 to Zhou Yanan*

already add slew quick button (1x/3x/5x) in IOS Slew interface, please update software and check it.

**#5 - 06/10/2025 02:18 PM - Zhou Yanan**

*- Status changed from 　　/BeVerified to 　　/InProgress*

*- Assignee changed from Zhou Yanan to 　*

The speed of movement on the flight path is currently not strong enough. Please increase it by another 10X.

**#6 - 06/10/2025 03:26 PM - 　**

*- Assignee changed from 　 to Zhou Yanan*

already add slew quick button (10x) in IOS Slew interface, please update software and check it.