Problems with daily training and usage - 11 /Bug #1319

The runways of some general airports are incorrect

05/16/2025 06:41 PM - Zhou Yanan

Status: 05/16/2025

Priority: Medium % Done: 0%

Assignee: sim tech Spent time: 0.00 hour

Category:

Target version:

Reporter:YANAN ZHOUFlightPhase:LandingPhone:NA100%Reproducible:YES

PlannedFixDate: 05/21/2025 ReproductionSteps: reposition to final 3nm

SoftVersion: a320-1.9.15 IssueType: Visual

Description

The runways of RPLC and VOBL airports are displayed as having two, but in reality, there should only be one. Adjustments are needed

History

#1 - 05/16/2025 10:42 AM - Zhou Yanan

- Status changed from [] [] [] /Remains to [] [] [] /InProgress

The AIP needs to be obtained to update the runway information

#2 - 05/20/2025 03:27 PM - Zhou Yanan

- Reporter set to YANAN ZHOU
- Phone set to NA
- PlannedFixDate set to 05/21/2025
- SoftVersion set to a320-1.9.15
- FlightPhase set to Landing
- 100%Reproducible set to YES
- ReproductionSteps updated

RPLC is fixed

After confirming with the captain, it was confirmed that a runway was missing from the VOBL visual view

#3 - 05/27/2025 08:51 AM - 🛭 🗎

- Status changed from [] [] [] /InProgress to [] [] /FeedBack
- Assignee changed from [] [] to Zhou Yanan

After updating the airport configuration file Custome Runway Data.txt I, the VOBL Airport has added a required runway.

#4 - 06/09/2025 10:09 AM - Zhou Yanan

- Assignee changed from Zhou Yanan to sim tech

VOBL airport is now operating normally.

08/08/2025 1/1