

Problems with daily training and usage - /Bug #1345

No motion cues for Engine compressor stall malfunction

05/30/2025 04:48 AM - sim tech

Status:	InProgress	Start date:	05/29/2025
Priority:	Medium	% Done:	0%
Assignee:		Spent time:	0.00 hour
Category:			
Target version:			
Reporter:	Hugues Lemire	FlightPhase:	Takeoff
Phone:	09063489642	100%Reproducible:	YES
PlannedFixDate:	06/04/2025	ReproductionSteps:	Init Step Issue Expect
SoftVersion:	a320-1.9.15	IssueType:	Motion&Bridge
Description When performing a takeoff and setting the Engine compressor stall malfunction to kick in at V1 speed, you can hear the sound and see the visual effects but no motion cues are felt			

History

#1 - 06/04/2025 02:05 PM - Zhou Yanan

- Status changed from /Remains to /New

- Assignee changed from Zhou Yanan to

#2 - 08/04/2025 05:11 PM -

- Status changed from /New to /InProgress

#3 - 08/04/2025 05:11 PM -

- IssueType Motion&Bridge added

- IssueType deleted (CLS)

#4 - 08/07/2025 11:06 AM - Hugues Lemire

Tested during our last quality flyout and the crew deemed that this motion cue is too light and needs more tuning.