

Problems with daily training and usage - /Bug #1351

No landing gear pins displayed behind Capt. seat

05/30/2025 04:59 AM - sim tech

Status:	/FeedBack	Start date:	05/29/2025
Priority:	Medium	% Done:	0%
Assignee:	sim tech	Spent time:	0.00 hour
Category:			
Target version:			
Reporter:	John Ramos	FlightPhase:	N/A
Phone:	09063489642	100%Reproducible:	YES
PlannedFixDate:	06/04/2025	ReproductionSteps:	Init Step Issue Expect
SoftVersion:	a320-1.9.15	IssueType:	Hardware&Structure
Description			
Landing gear pins should be displayed behind Capt. seat			

History

- #1 - 06/04/2025 01:36 PM - Zhou Yanan
- Status changed from /Remains to /FeedBack
 - Assignee changed from Zhou Yanan to sim tech

The landing gear pins need to be printed by oneself.