

Problems with daily training and usage - /Bug #1473

No aural EGPWS warning on NEO

09/25/2025 08:32 AM - sim tech

<b>Status:</b>	/FeedBack	<b>Start date:</b>	09/25/2025
<b>Priority:</b>	Medium	<b>% Done:</b>	0%
<b>Assignee:</b>	sim tech	<b>Spent time:</b>	0.00 hour
<b>Category:</b>			
<b>Target version:</b>			
<b>Reporter:</b>	simtech	<b>FlightPhase:</b>	N/A
<b>Phone:</b>	09063489642	<b>100%Reproducible:</b>	YES
<b>PlannedFixDate:</b>	10/02/2025	<b>ReproductionSteps:</b>	Init:
			Step:
			Issue:
			Expect:
<b>SoftVersion:</b>	a320-1.9.15	<b>IssueType:</b>	Others
<b>Description</b>			
during cycle C flyout, test pilot did not hear aural warning on EGPWS. They tried it 3 times			

History

- #1 - 09/25/2025 10:10 AM - Zhou Yanan
- Status changed from /Remains to /FeedBack
  - Assignee changed from Zhou Yanan to sim tech

It could be that the pilot's operation failed to reach the threshold for triggering the alarm. However, it could also be that there is an anomaly in the output of the EGPWS sound signals. One can try to position the aircraft to 3nm and cause it to crash into the ground, then check if there is a "PULL UP" voice alert. If there is no such voice notification, the sound system can be reboot on the management computer.