

Problems with daily training and usage - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated	PlannedFixDate
1354	☐☐/Bug	☐☐/New	Medium	Router UI is in Chinese only	☐ ☐☐	06/04/2025 09:37 PM	06/04/2025
1353	☐☐/Bug	☐☐☐/InProgress	Medium	Debrief Camera UI is in Chinese only	Zhou Yanan	06/30/2025 01:23 PM	06/04/2025
1352	☐☐/Bug	☐☐/New	Medium	Ambient Light LEDs that are simulating sunlight are white	☐ ☐☐	06/04/2025 09:37 PM	06/04/2025
1351	☐☐/Bug	☐☐/FeedBack	Medium	No landing gear pins displayed behind Capt. seat	sim tech	06/04/2025 09:36 PM	06/04/2025
1350	☐☐/Bug	☐☐☐/InProgress	Medium	NW Steering fault should show "CAT III Dual" in inop system on STS page	☐ ☐☐	06/08/2025 10:26 AM	06/04/2025
1348	☐☐/Bug	☐☐/FeedBack	Medium	Emergency service vehicles are not available on any runways	sim tech	08/07/2025 10:15 AM	06/04/2025
1347	☐☐/Bug	☐☐/FeedBack	Medium	UPRT and Windshear handling is too easy	sim tech	06/27/2025 07:56 AM	06/04/2025
1346	☐☐/Bug	☐☐☐/InProgress	Medium	Aircraft position slew on the IOS is too slow	Zhou Yanan	06/10/2025 03:26 PM	06/04/2025
1345	☐☐/Bug	☐☐☐/InProgress	Medium	No motion cues for Engine compressor stall malfunction	☐ ☐☐	08/07/2025 11:06 AM	06/04/2025
1344	☐☐/Bug	☐☐/FeedBack	Medium	Emer Elec config fail	sim tech	08/01/2025 03:05 PM	06/04/2025
1343	☐☐/Bug	☐☐☐/InProgress	Medium	Sound not audible	☐ ☐☐	08/07/2025 10:44 AM	06/04/2025
1329	☐☐/Bug	☐☐☐/InProgress	Medium	RNAV RPLL 06 FLS not aligned with PAPI	☐ ☐	05/22/2025 04:41 AM	08/31/2025
1328	☐☐/Bug	☐☐/FeedBack	Medium	Problems with daily training and usage	sim tech	05/26/2025 11:45 PM	05/31/2025
1325	☐☐/Bug	☐☐/FeedBack	Medium	TRAFFIC APPEAR (B747) ON TOP AFTER PUSH BACK. REFERENCE AIRPORT RPLC	sim tech	05/23/2025 11:00 PM	05/31/2025
1324	☐☐/Bug	☐☐/FeedBack	Medium	NO LOCKING MECHANISM FOR THE DOOR OF THE SIMULATOR.	sim tech	05/19/2025 10:05 PM	05/31/2025
1323	☐☐/Bug	☐☐/FeedBack	Medium	NOT ENOUGH YAW MOVEMENT DURING ENGINE FAILURE WITH DAMAGE	sim tech	05/27/2025 05:12 PM	05/31/2025
1321	☐☐/Bug	☐☐/FeedBack	Medium	LANDING MEMO NOT DISPLAYED DURING DESCEND PAST 1000 FT RA FROM REPOSITION. IT ONLY APPEAR AT 700 FT RA	sim tech	05/19/2025 10:12 PM	05/31/2025
1320	☐☐/Bug	☐☐/FeedBack	Medium	TRAFFIC ON RUNWAY CANNOT BE REMOVED (DESPITE RUNWAY INCURSION INACTIVE)	sim tech	08/01/2025 03:23 PM	05/31/2025
1319	☐☐/Bug	☐☐/FeedBack	Medium	The runways of some general airports are incorrect	sim tech	06/09/2025 10:09 AM	05/21/2025
1318	☐☐/Bug	☐☐☐/BeVerified	Medium	The oxygen value of the oxygen cylinder cannot be set directly	Zhou Yanan	06/11/2025 01:55 PM	05/23/2025