

Problems with daily training and usage - /Bug #1326

Wrong Navigation Data RWY 27L/09R VOBL

05/17/2025 04:50 AM - sim tech

Status:	/Closed	Start date:	05/16/2025
Priority:	Medium	% Done:	0%
Assignee:	sim tech	Spent time:	0.00 hour
Category:			
Target version:			
Reporter:	Sim tech	FlightPhase:	Takeoff
Phone:	03063489642	100%Reproducible:	YES
PlannedFixDate:	05/31/2025	ReproductionSteps:	Init Step Issue Expect
SoftVersion:	a320-1.9.15	IssueType:	Visual
Description Training crew comment: "Negative RWY 27L/09R VOBL" As they approach, the runway was not visible and it was because the navigation data was not correct.			

History

#1 - 05/19/2025 09:15 AM - Zhou Yanan - Project changed from A320 AAG FFS#1 After-sales maintenance project to Problems with daily training and usage - Status changed from /Remains to /New - Reporter deleted (Sim tech) - Phone deleted (03063489642) - PlannedFixDate deleted (05/31/2025) - SoftVersion deleted (a320-1.9.15) - FlightPhase deleted (Landing) - 100%Reproducible deleted () - ReproductionSteps updated
#2 - 05/19/2025 09:21 AM - Zhou Yanan - Reporter set to Sim tech - Phone set to 03063489642 - PlannedFixDate set to 05/31/2025 - SoftVersion set to a320-1.9.15 - FlightPhase set to Takeoff - 100%Reproducible set to YES - ReproductionSteps updated
#3 - 05/20/2025 03:29 PM - Zhou Yanan - Assignee changed from Zhou Yanan to - IssueType Visual added - IssueType deleted (SoftSystem(FunctionLogic))

#4 - 05/27/2025 08:45 AM -

- Status changed from /New to /BeVerified
- Assignee changed from to Zhou Yanan

After updating the airport configuration fileCustomRunwayData.txt, the airport model can be displayed normally.

#5 - 05/27/2025 09:14 AM - Zhou Yanan

- Status changed from /BeVerified to /FeedBack
- Assignee changed from Zhou Yanan to sim tech

#6 - 07/01/2025 02:49 PM - sim tech

- Status changed from /FeedBack to /Closed