

Problems with daily training and usage - /Bug #1337

6NM & 9NM repositions have the same altitude / Height above terrain

05/30/2025 12:53 AM - sim tech

Status:	/Closed	Start date:	05/29/2025
Priority:	Medium	% Done:	0%
Assignee:	sim tech	Spent time:	0.00 hour
Category:			
Target version:			
Reporter:	Hugues Lemire	FlightPhase:	Landing
Phone:	09063489642	100%Reproducible:	YES
PlannedFixDate:	06/04/2025	ReproductionSteps:	Init Step Issue Expect
SoftVersion:	1	IssueType:	Visual
Description 6NM & 9NM repositions have the same altitude / Height above terrain. the 9NM reposition should be higher than the 6NM one			

History

- #1 - 06/04/2025 04:51 PM - Zhou Yanan
- Status changed from /Remains to /New

- Assignee changed from Zhou Yanan to
- #2 - 06/05/2025 11:13 AM -
- Status changed from /New to /BeVerified

- Assignee changed from to Zhou Yanan
- Yanan zhou will change config on site to fix this problem
- #3 - 06/05/2025 11:41 AM - Zhou Yanan
- Status changed from /BeVerified to /FeedBack
- The adjustment has been completed.
- #4 - 06/05/2025 11:41 AM - Zhou Yanan
- Assignee changed from Zhou Yanan to sim tech
- #5 - 08/07/2025 10:47 AM - Hugues Lemire
- Status changed from /FeedBack to /Closed