

Problems with daily training and usage - /Bug #1343

Sound not audible

05/30/2025 04:29 AM - sim tech

Status:	InProgress	Start date:	05/29/2025
Priority:	Medium	% Done:	0%
Assignee:		Spent time:	0.00 hour
Category:			
Target version:			
Reporter:	Shiella Caling	FlightPhase:	N/A
Phone:	09063489642	100%Reproducible:	YES
PlannedFixDate:	06/04/2025	ReproductionSteps:	Init Step Issue Expect
SoftVersion:	a320-1.9.15	IssueType:	Sound
Description			
Sound of tire burst is not audible			
SIMTECH checked the malfunction for tire bursts, it has a sound but it's not enough. An requested that a captain should be here during the sound adjustment so that they can adjust it to their liking.			

History

- #1 - 06/04/2025 02:52 PM - Zhou Yanan
- Status changed from /Remains to /InProgress
- #2 - 08/01/2025 03:01 PM - Zhou Yanan
- Assignee changed from Zhou Yanan to
- #3 - 08/07/2025 10:44 AM - Hugues Lemire
- Tested last July 15th and the crew said the sound for tire bursts needs to be increased. Mr. An said a Captain needs to be there during the sound adjustment so it can be adjusted to their liking.