Problems with daily training and usage - 11 /Bug #1344

sim tech

Emer Elec config fail

05/30/2025 04:31 AM - sim tech

Status: Start date: 05/29/2025

Spent time:

Priority: Medium % Done: 0%

Assignee: Category:

Target version:

Reporter:Shiella CalingFlightPhase:N/APhone:09063489642100%Reproducible:YESPlannedFixDate:06/04/2025ReproductionSteps:Init□

Step[]

Issue

Expect[]

0.00 hour

SoftVersion: a320-1.9.15 IssueType: Others

Description

During Emer Elec config, Gen 1 and 2 fail, APU Gen will not cut in

CSS needs more information. Please ask Capt. Harris or Capt. Dennis for more information so we can provide it to CSS.

History

#1 - 06/04/2025 02:51 PM - Zhou Yanan

- Status changed from [] [] [] /Remains to [] [] [] /InProgress

#2 - 08/01/2025 03:05 PM - Zhou Yanan

- Status changed from [] [] [] /InProgress to [] [] /FeedBack
- Assignee changed from Zhou Yanan to sim tech

The last time we conducted a flight out with the captains, no abnormalities were detected.

08/08/2025 1/1